

CODE NO: CC-236

DATE: FEBRUARY 26, 1992

SUBJECT: V-SPRINGS FOR PLASTIC SIDE PANELS (ALL 1990 TO 1992 GARDEN & SUPER GARDEN TRACTORS)

PROBLEM: IT HAS BEEN REPORTED THAT SOME OF THE PLASTIC SIDE PANELS DO NOT STAY SECURED AT THE TOP.

SOLUTION: INSTALL THE V-SPRINGS INTO THE LOCKING PIN AS SHOWN BELOW. THE V-SPRINGS SHOULD BE INSTALLED 90 DEGREES TO THE SLOT. THE V-SPRING CAN BE INSTALLED WITH A SCREW DRIVER AND SHOULD BE PUSHED IN UNTIL IT IS JUST BELOW THE END OF THE LOCKING PIN.

INSTALLING THE V-SPRING SHOULD ONLY BE NECESSARY IN THE TOP LOCKING PIN ONLY. A PACK OF 10 V-SPRING (732-3078) HAVE BEEN INCLUDED WITH THE ORIGINAL MAILING OF THIS BULLETIN.

IF ADDITIONAL SPRINGS ARE NEEDED, ORDER THROUGH THE CUB CADET PARTS DEPOT.

